



April 21, 2017

Page 1 of 1

---

***External Notice: NovAtel Announces End of Life  
for Multiple OEM6<sup>®</sup> Receiver Boards***

NovAtel Inc. is announcing the End of Life of the:

**OEM615, OEM617, and OEM628 series boards** (see discontinued part numbers below)

These products will be available for order until:

**September 29, 2017** (or until inventory is depleted)

Shipments may be scheduled for no later than:

**March 30, 2018**

NovAtel will continue to support and repair these products until:

**September 30, 2020**

For a complete list of affected part numbers and the associated replacement part numbers, please refer to the table below:

<b>Discontinued Part Number</b>	<b>Replacement Part Number</b>
OEM615-xxx-xxx-xxx	OEM719-
OEM615A-xxx-xxx-xxx	OEM719A-
OEM615B-xxx-xxx-xxx	OEM719B-
OEM615C-xxx-xxx-xxx	OEM719C-
OEM615V-xxx-xxx-xxx	OEM719-
OEM617-xxx-xxx-xxx	OEM719-
OEM617B-xxx-xxx-xxx	OEM719B-
OEM628-xxx-xxx-xxx	OEM729-
OEM628C-xxx-xxx-xxx	OEM729C-
OEM628E-xxx-xxx-xxx	OEM729-
OEM628V-xxx-xxx-xxx	OEM729-

Notes:

- OEM617D, OEM625, and OEM638 series boards are not covered by this EOL document and continue to be available until further notice
- Software models between OEM6 and OEM7<sup>®</sup> are defined differently. For information on the OEM7 series receivers, please visit the NovAtel website:  
<http://www.novatel.com/products/gnss-receivers/oem-receiver-boards/oem7-receivers/>